## Nº 7273 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7/8/60	_ IF SO HOW AND LOCATION FROM
HOUSE NO. 1/24	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH 58
WAS LATERAL AT CURBA YES	
WAS ATTACHED TO MAIN YES	- NAME OF CONTRACTOR - George Sedon
SHOW BY DIAGRAM RELATION OF LAT	· · · · · · · · · · · · · · · · · · ·
on and the second s Second second	80 N
nagain na kata di Barata da ang katawa a ka	
5/M 81/D	27' 8'0 FLOW
SIGNED Milliam ( Mill) INSPECTOR FOR C	HTY CONTROL OF SUCCESSION OF S

## G3367 Nº 17273

## PERMIT TO TAP SEWER

	ing the state of t	graveski i kra Prima kran <b>Massillo</b> i	N, OHIO, Juli	1 719
RECEIVED OF	Lenge		1 1	FEE OF S
FOR WHICH PERMISS		Taimer & & >	I find	
TO TAP		SEWER ON THE	East	
or_1410	Ch. EW.	AVE. ST. TYPE OF STREE	That d	
THE PREMISES BEING	LOT NO. 9963	-64	HOUSE NO	124
WORK TO BE DONE RULES OF THE DEPA			323, DULY PASSED	BY THE CITY COUNCIL

NAME OF CONTRACTOR HOTOR Sedans

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.