## Nº 7277

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7/11/40	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. /8 62	<u> </u>
SIZE OF PIPE USED_6"	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH 103 555 D
WAS LATERAL AT CURBY YES	and <u>a communicación</u> de protecto en el Egypto de Egypto en el composito de la composito della
WAS ATTACHED TO MAIN YES	NAME OF CONTRACTOR #. V. DIFNIT
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED.
en de la proposition de la compansión de l La compansión de la compa	na karangan dan kar Barangan dan karangan dan karang
	FLOW - 12 -
SIGNED William CMD	FILED AT ENGINEER'S OFFICE
INSPECTOR FOR C	

## 10-8-60

## Nº2 7277 CERTICE OF THE DIRECTOR OF PUBLIC SERVICE

		MASSILLON, O	410, <u> </u>	
RECEIVED OF /	(P)	$m \leq \ell$		FEE OF \$ 0
	SEV	VER ON THE	e gar	
- 2nd 77	AVE. ST. TY	PE OF STREET	Hard	200 mayor
HE PREMISES BEING LOT NO	7790	, но	DUSE NO. /6	<del>2 </del>

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL

Name of Contractor\_\_\_\_\_\_

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.