Nº 7278

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7/15/60	FIRST MANHOLE DOWN STREAM 56,5 FROM UPSTREAM NOT 5.50
HOUSE NO	
SIZE OF PIPE USED6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? NO	and the second of the second o
	NAME OF CONTRACTOR REMELY
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
and the second of the second o	19'
	78 7 5.50
en er	en 1906 et 1905 per un la remujo sepero K. Ed Louis B. Lea (S. Lierus). Le remons de la remojo de Rube de La semble de 1908 per 1908 per 1908.
•	25
	FZ 57:5;W,
SIGNED Milliam E. Milo	EU ED AT ENGINEERIG OFFICE
/ INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE

2-15		Lande	onat		
10-25-6	Gerge ve ee		OFFICE OF THE	DIRECTOR OF PUE	LIC SERVICE
	THE RESIDENCE $N_{f 0}$	7278	PERMIT	Γ TO TAP SE	WER
				7/	
		and the State of	MASSILL	ON, OHIO, ///	19
	•	ECEIVED OF	P		-a
	· · · · · · · · · · · · · · · · · · ·	a a section	3. 1/1/20		FEE OF 5
	FOR WH	CH PERMISSION IS GRANTED		1-0-1-0-1	
	TO TAP_	Acces	SEWER ON TH	HE (1).	
	ee or_G	+10 /10	AVE, ST. TYPE OF STR	HEET House	Aurta
	THE PRE	MISES BEING LOT NO.	R10	, HOUSE NO	
			-		
	WORK T	BE DONE IN ACCORDANC	E WITH ORDINANCE NO.	2323, DULY PASSED BY T	HE CITY COUNCIL
	RULES	F THE DEPARTMENT OF PU	BLIC SERVICE.		
					2
		_ /\	$\mathcal{L}_{\mathcal{L}}$		****
	NAME O	CONTRACTOR/	comey-		
	·		. ()		
The second of the second secon		ote This permit co			
	walls	of building is subjec	t to Massillon Boar	rd of Health Regula	tions.
	an programa de la companya da camba da may may may may may may may may may ma	and the second s	And the second section of the second section of the second section of the second section of the second section		