## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 7280 AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO.	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH
WAS LATERAL AT CURB?	and was the state of the state
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LAT	
Ellering by the process of the control of the contr	No INSPECT
	No Inspection on This sewer LAT
SIGNED TO THE TOTAL CONTROL OF THE STATE OF	FILED AT ENGINEER'S OFFICE

## Nº 7280 PERMIT TO TAP SEWER

	$\sqrt{c_2}$ variety design $\sqrt{c_2}$ and $\sqrt{c_3}$ variety $\sqrt{c_4}$ and $\sqrt{c_4}$ variety $c_4$
The state of the s	MASSILLON, OAIO,
• 1	RECEIVED OF FEE OF 5
ر	in the property of the Party of the property of the party
<i>~</i>	FOR WHICH PERMISSION IS GRANTED THE TOTAL COLOR
•	
	TO TAPSEWER ON THE
	of 2 h
	THE PREMISES BEING LOT NO. 835, HOUSE NO. 853
	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
	RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
	No. 10 and 5 and 10 and

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.