Nº 7281

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7/16/65	IF SO HOW AND LOCATION FROM 9'FROM UPSTREEM MY. 8'D.
HOUSE NO. 9/7	
SIZE OF PIPE USED 6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? NO	and the financial control of the first of th
	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING, SERVED.
	BACK OF HOUSE
and the state of t	- Continue of the Continue of
. The world free was to be a warm of the constant of the const	romanica no laborar allas filosoficia de región de regionarios
•	
	80 DEFO END N
will enter	THIS IS APPROX. MER SUREMENT
SIGNED Tilles E. White INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE
一一、一、一、一、我一样一、白人,就是是特性自然一种的知识的	March March I All got tradified a subtrack that will be a fille by

通りできる字形と 文章 (自文本集)を終入 とき かき OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

SEMEN NO 7281 COMMON AMPERMIT TO TAP SEWER MASSILLON, OHIO,

THE PREMISES BEING LOT NO. 1575, HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.