Nº 7292

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED 8-18-60 | IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM |
|---|---|
| HOUSE NO. 955 | |
| SIZE OF PIPE USED 6 1/ | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH SOUTH STATE CURB LINE AND DEPTH |
| WAS LATERAL AT CURBY VTS | |
| WAS ATTACHED TO MAIN | NAME OF CONTRACTOR RMarks |
| SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED. | |
| | 19' |
| | 7'DD |
| | $\frac{\langle c' \rho \rho \rightarrow \sqrt{g'} \rangle}{\langle c' \rho \rho \rightarrow \sqrt{g'} \rangle}$ |
| SIGNED Roy Lathan | FILED AT ENGINEER'S OFFICE |
| NSPECTOR FOR CIT | |

NO 7292 OF THE DIRECTOR OF PUBLIC SERVICE

RECEIVED OF MASSILLON, OHIO, (1970) 19

RECEIVED OF MASSILLON, OHIO, (1970) 19

FEE OF \$ 55

FOR WHICH PERMISSION IS GRANTED (1970) 19

SEWER ON THE (1970) 19

OF 28th 19 W AVE. TYPE OF STREET (1970) 19

THE PREMISES BEING LOT NO. 12140 1900 1905

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR & MANGE OF CONTRACTOR

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.