Nº 7310

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED //- 25-6	O IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	6/2 De.
HOUSE NO. 2233		
SIZE OF PIPE USED 611	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? NO	i de la distribución de la companya de la companya La companya de la co	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Joe & Ja	
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING SERVED.	18'
		0,12
	the second secon	32
	N A A A A A A A A A A A A A A A A A A A	7' CELVAD
SIGNED ROY Latter		
INSPECTOR FOR CI	FILED AT ENGINEER'S OFFICE	- Carle 2
REMARKS		•

STALL OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

ist. 1907 – Sagar Santa s 1908 – Santa S	ILLON, OHIO, QUA 97 19
RECEIVED OF 91.9 & Holdes	FEE OF \$ 35
FOR WHICH PERMISSION IS GRANTED	
TO TAP SEWER ON	THE Louth
of Munitan ave. ST. Type of s	
THE PREMISES BEING LOT NO. # 13/16	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO	
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.