Nº 7314

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

	57 W. OJ /.
DATE INSPECTED	IF SO HOW AND LOCATION FROM TAPPED Brookfield TVUNK
HOUSE NO. 22/2	FIRST MANHOLE BOWN STREAM 1777 7 C CO 1007 3 7 5 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURBI NO	
WAS ATTACHED TO MAIN VF.5	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	6 V t
	. The contribution of the ${\cal G}$ is the ${\cal G}$ in the ${\cal G}$
	130 17' 84 0
Rod Latte	TAPPED WITH SADDLEY 11 PROPERTY OFFICE 45° BEND
SIGNED INSPECTOR FOR CIT	Y
	industria considerate albitus la citare y 2-6-6%

Nº 7314

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

and the second of the second o			* .
	Massillon, Ohio	. Clug 27	19
RECEIVED OF 77 4	Idas 1		FEE OF S 5
. /			1.7
FOR WHICH PERMISSION IS GRANTED	10		
TO TAP	WER ON THE	with	
A.1			
OF MININGS HOW ST. TI	PE OF STREET	Land C	· Inai
THE PREMISES BEING LOT NO. 12/2/	9	201	
THE PREMISES BEING LOT NO. 1 217 217	, ноиз	E NO. 27 7 2	
WORK TO BE DONE IN ACCORDANCE WITH ORDIN	ANCE No. 2323, DU	LY PASSED BY TH	E CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.			
			•
NAME OF CONTRACTOR	-l		
Note This permit covers work	outside of buil	ding only. A	Any work in

walls of building is subject to Massillon Board of Health Regulations.