

Nº 7319

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

149' W. 8th N. 12' D

DATE INSPECTED 11-28-60

IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM TAPPED Brookfield Trunk

HOUSE NO. 2225

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Joe Inc

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



149' Tapped with SADDLE 45° B. & N. D.

SIGNED Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

2-28-62

8-42

8-42

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

NO 7319

PERMIT TO TAP SEWER

MASSILLON, OHIO, Aug 27 1942

RECEIVED OF Mr. S. B. B. B. FEE OF \$ 5.00

FOR WHICH PERMISSION IS GRANTED Same

TO TAP San SEWER ON THE South

OF Mayflower NW AVE. ST. TYPE OF STREET Hard Surface

THE PREMISES BEING LOT NO. 12126 HOUSE NO. 2228

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Joe & Joe

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.