## Nº 7322

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3-3-6/	FIRST MANHOLE STREAM 49 NovTH of M. 7 Ner	
HOUSE NO. 709	UP	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH	
WAS LATERAL AT CURB? YPS		
WAS ATTACHED TO MAIN YES	NAME OF CONTRACTOR SEE X LONG	
SHOW BY DIAGRAM RELATION OF LATE		
tana Mandala sa tanga tanga at mengalah mengalah banda di sebagai salah berasa dan sebagai sebagai sebagai seb Mandalah sebagai sebag Mandalah sebagai sebag	70	
	-N sturm 38.	
	70 14	
SIGNED Roy Latham   INSPECTOR FOR CI		
REMARKS	History Court and the Control of the	
H F M A H K S		

8-12

## $\mathbf{N}$ 2 $^{\circ}$ 7322

## PERMIT TO TAP SEWER

	MASSILLON, OHIO, Aug 27 19	
RECEIVED OF 11.7 & 1914	FEE OF S S	
FOR WHICH PERMISSION IS GRANTED Scare		
TO TAP SO .~	VER ON THE West	
OF Standish 11 W AVE. TYP	DE OF STREET HAND Surface	
THE PREMISES BEING LOT NO. 12/29	, HOUSE NO. 7/9	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.		
NAME OF CONTRACTOR		

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.