## Nº 7344

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9-7-60 IE SO HOW	
DATE 1110: 40: 40	AND LOCATION FROM HOLE DOWN STREAM
28/3	
SIZE OF PIPE USED 6" UP BOWN STRE	AND DEPTH 133 mys stream H 6 Dee
WAS LATERAL AT CURBY Yes	and the second s
WAS ATTACHED TO MAIN YCS NAME OF	CONTRACTOR & Muhan
SHOW BY DIAGRAM RELATION OF LATERAL TO WA	LL OF BUILDING SERVED.
	The aprel
estado estado de tentro de alta en entre entre en entre entr	
a de la companya de l	of the following the state of t
the state of the s	n' & G been
n J-	133 up Stram M
SIGNED / W WAREN	FILED AT ENGINEER'S OFFICE
	Akarti (Bosa digeli disela di titera)
REMARKS	

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

TO TAP WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.