

Nº 7346

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-3-60

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 714

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

39' SOUTH OF M 5 1/2' DEEP


WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR

H. Urban

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED _____

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

7-22
10-25-60

✓
No 7346

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

19

RECEIVED OF

Harry B. Urban

FEE OF \$

5⁰⁰

FOR WHICH PERMISSION IS GRANTED

Carl New

TO TAP

RAW

SEWER ON THE

east

OF

12th S.W.

AVE.

ST. TYPE OF STREET

alld

THE PREMISES BEING LOT NO.

4664

HOUSE NO.

714

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Harry B. Urban

Note This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.