

Nº 7354

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-7-60

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. _____

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN NX

NAME OF CONTRACTOR R. Penley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Roy Lathin

INSPECTOR FOR CITY

EAST CURB

5TH ST

FILED AT ENGINEER'S OFFICE

REMARKS _____

10-25-60

Relay

No 7354

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 10/20/60

RECEIVED OF

R. Remley

FEE OF \$ 5.⁰⁰

FOR WHICH PERMISSION IS GRANTED

Bd of Ed

TO TAP

Assn

SEWER ON THE

East Side of 5th

OF

5th N.E.

AVE.

ST. TYPE OF STREET

Paved

Longfellow Sch.

THE PREMISES BEING LOT NO.

580

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

R. Remley

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.