

Nº 7358

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-28-60

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 311

SIZE OF PIPE USED 6" UP

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

162' west of MH 7' deep



WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR

N. Urban

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Roy Lathan
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

16-35-36

11-28-60 ✓

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 7358

PERMIT TO TAP SEWER

MASSILLON, OHIO, 10/27 1960

RECEIVED OF

Glick Bros

FEE OF \$ 5.00

FOR WHICH PERMISSION IS GRANTED

Same

TO TAP

San

SEWER ON THE

D

OF

Phone NE

AVE.

ST. TYPE OF STREET

Alced

THE PREMISES BEING LOT NO.

11197

HOUSE NO.

311

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

H. Urban

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.