FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 11-30-60	IF SO HOW AND LOCATION FROM WYY 63 F. OF M 9 DEFE
HOUSE NO. 44	
SIZE OF PIPE USED	DISTANCE FROM-FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? No	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR————————————————————————————————————
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
	6
	2
	45°B »ND 9000 °C 25°
	MARKET 9 63'
SIGNED Roy Yathan	ALLY7
INSPECTOR FOR CIT	ราย (เมื่อสาราชาวิทา (1 200) เมื่อสุด (1 200) เป็นสาราชาวิทา (1 200)
REMARKS	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

Marlon	· · · · · · · · · · · · · · · · · · ·	FEE OF \$
Missiller	auf S	
SEWER ON TH		

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR TO ST MICE AND

THE PREMISES BEING LOT NO. 99

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.