N^{o} 7372

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 11-14-60 IF SO HOW AND LOCATION FROM
HOUSE NO 548 FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED CURB LINE AND DEPTH 40 North of UP STYPAM THE
WAS LATERAL AT CURB? Yes
WAS ATTACHED TO MAIN NAME OF CONTRACTOR A Liana.
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
70p
and the first of t
7'07
SIGNED Por Lathan FILED AT ENGINEER'S OFFICE
INSPECTOR FOR CITY OF THE PROPERTY OF THE PRO
REMARKS

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

en e	MASSILLON, OHIO, 19
RECEIVED OF A. A. Dia	FEE OF 5
FOR WHICH PERMISSION IS GRANTED	+ Kitson
TO TAP SE	EWER ON THE
of 24 7/11 AVE. TY	and the second of the second o
THE PREMISES BEING LOT NO. 120.54	. HOUSE NO. 548
the state of the s	AND AND ARRANGE FOR COMMON

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR G. J. M. COLAR

Note This permit covers work outside of building only. Any work ir walls of building is subject to Massillon Board of Health Regulations.