Nº 7391

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3-13-61	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. //27	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 103 SHUTH OF MI SIA DEP
WAS LATERAL AT CURB? /- 5	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR, Beaver Const
SHOW BY DIAGRAM RELATION OF LATER	
and the second s	35
o de la composição de la Composição de la composição de la composiç	9/1
	N
	en de la companya de La companya de la co
	La Arro manara de la contra de la FL Deer 17
SIGNED ROY atham	EU 50 AT ENGINEERIS
INSPECTOR FOR CITY	
REMARKS	

1 PERMIT TO TAP SEWER

:	MASSILLON, OHIO, March 15 19
	RECEIVED OF Brown & Higher Borner FEE OF \$ 5=
	RECEIVED OF MOUNT (1) - A DORNAL FEE OF S ()
	FOR WHICH REPAYED AND COMPANY
	FOR WHICH PERMISSION IS GRANTED
	TO TAP SEWER ON THE 1100 T
	OF The Ju. AVE. ST. TYPE OF STREET Aut
	THE PREMISES BEING LOT NO. 2983 - 4 , HOUSE NO. 1127
	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
	RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
	A. C.

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.