

Nº 7415

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 5-20-61

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 529

SIZE OF PIPE USED 6" UP


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 113' North Ho Fop stream MH @ HOWARD

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR D. Rogers

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

NOTORIOUSLY VIOLATING THE PROHIBITION OF THE OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

~~17-13~~ No 7415

PERMIT TO TAP SEWER

17-13

8-21-61

MASSILLON, OHIO,

5-19

19

RECEIVED OF

Dale Rogers & Sons

FEE OF \$ *5.00*

FOR WHICH PERMISSION IS GRANTED

Glennwood Home

TO TAP

San

SEWER ON THE

West

OF

25th 7120

AVE.

ST. TYPE OF STREET

Dist

THE PREMISES BEING LOT NO.

7076

HOUSE NO.

529

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Dale Rogers & Sons

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.