

Nº 7422

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6-27-61

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1410

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

77' E. of MH 8' DEED

WAS LATERAL AT CURB? _____


OP. Ramsey
D. Ramsey

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N
297
327
171
306



SIGNED _____

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

3-32
7-29-61

Nº 7422 ✓

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, June 9 1961

RECEIVED OF

Wale Rogers & Sons

FEE OF \$

5.00

FOR WHICH PERMISSION IS GRANTED

Glendale Homes

TO TAP

San

SEWER ON THE

North

OF

Lake NE

AVE.
ST.

TYPE OF STREET

Hard surface

THE PREMISES BEING LOT NO.

6106

HOUSE NO.

140

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Wale Rogers & Sons

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.