

Nº 7443

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6-27-61

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 827

SIZE OF PIPE USED 6"



DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT 89' SOUTH OF M.H. 6' DEEP
CURB LINE AND DEPTH

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR URBAN

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Ronald M. Hatter
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

~~16-50~~

16-50

8-21-61

Nº 7443

OFFICE OF THE DIRECTOR OF PUBLIC SEWERS
PERMIT TO TAP SEWER

MASSILLON, OHIO.

7/27

RECEIVED OF

H. J. Barker

FEE OF \$

5.00

FOR WHICH PERMISSION IS GRANTED

(H. J. Barker)

TO TAP

San

SEWER ON THE

W

OF

W. J. Barker - 718

AVE.

ST. TYPE OF STREET

Dist

THE PREMISES BEING LOT NO.

11940-41

HOUSE NO.

827

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

H. J. Barker

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.