7449

 N_{i}^{o}

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-9-61	IF SO HOW AND LOCATION FROM 1 1 133 West of 14 8 0
HOUSE NO. 257 2//6	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? No	and the control of th
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR E. LAUGHLIN
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
	20'
1	110 RHode ISLAWD
SIGNED Roy Latha	30 BIND 7 133'
V V INSPECTOR FOR CIT	

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO, Cara 7
RECEIVED OF Quality	1. Ever tice. FEE OF 5 05
FOR WHICH PERMISSION IS GRANTED	Trof Builders
TO TAP	SEWER ON THE WEST
Rhade Island JE	AVE. ST. TYPE OF STREET Shirt
THE PREMISES BEING LOT NO.	1231.5 HOUSE NO. 35 2116
WORK TO BE DONE IN ACCORDANCE	with Ordinance No. 2323, duly passed by the City Council, and

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.