Nº 7456

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-10-61	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 1200	
SIZE OF PIPE USED 6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 106 SO 4771 7 DEEP
WAS LATERAL AT CURB? YES	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR SEDON
SHOW BY DIAGRAM RELATION OF LATER	RAL TO WALL OF BUILDING SERVED.
N -7	10° TOEEP 10° BEND 10° BEND
SIGNED William Hummer INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE

Nº 7456

PERMIT TO TAP SEWER

	MASSILI	LON, OHIO, Clug	101
RECEIVED OF SCOT AC	Section	$\mathcal{O}_{\mathcal{O}}$	FEE OF \$
	Warneck	i year	
P	or we we exe	- Tachan	~
то тар <u>Хаш</u>	SEWER ON T	**	
of The Sw.	AVE. ST. TYPE OF STR	EET Stord	Surface
THE PREMISES BEING LOT NO. 570	66	, HOUSE NO	00.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR LATING Section

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.