

Nº 7457

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 8-21-61

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 300

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


17' WEST MH 10' DEEP

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR URBAN

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

William Hammer

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

16-33
12-6-61

✓
Nº 7457

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 8/15

RECEIVED OF

Geo. Hestler

FEE OF \$

5

FOR WHICH PERMISSION IS GRANTED

Same

TO TAP

San

SEWER ON THE

77

OF

Severy NE

AVE.

ST. TYPE OF STREET

Wood

THE PREMISES BEING LOT NO.

11532

HOUSE NO.

300

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

H. Urban

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.