Nº 7459

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED 9-22-63 | L IF SO HOW AND LOCATION FROM | : |
|--------------------------------|--|--------------|
| HOUSE NO. 74/ | FIRST MANHOLE DOWN STREAM | |
| SIZE OF PIPE USED | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT OUT WYY IN I CURB LINE AND DEPTH | 60' NorTHORM |
| WAS LATERAL AT CURB? NO | | 71/21 |
| WAS ATTACHED TO MAIN VES | NAME OF CONTRACTOR | Milan |
| SHOW BY DIAGRAM RELATION OF LA | TERAL TO WALL OF BUILDING SERVED. | |
| | 20' | |
| | - 1/6C' | |
| SIGNED ROY Sattle | FILED AT ENGINEER'S OFFICE | |
| INSPECTOR FOR | | |

17-29

Nº 7459

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

| | | Massillon, | Oisio, 1/1/1 | V6 |
|----------------------|---------------|-----------------------------|-------------------|-------------------|
| RECEIVED OF | 77.7.7% | 102472 | | 5 |
| FOR WHICH PERMISSIO | N IS GRANTED. | Elec Telec | | |
| TO TAP | | SEWER ON THE | | 4. 4. |
| OF / Co A CC | 10- 96 | AVE. _ST, TYPE OF STREET | | |
| THE PREMISES BEING L | | | HOUSE NO. 7 | 11 |
| | | RDINANCE No. 2323, DI | | C. L. C. |
| OF THE DEPARTMENT O | 247 147 | *DINANCE NO. 2323, DI | JLY PASSED BY THE | CITY COUNCIL, ANI |
| NAME OF CONTRACTOR | SMAROS | 3. Milau | | |

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.