

Nº 7462

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 7-25-61

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 2141

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


130' N. of M.H. 8' DEEP

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR A. J. DIANA

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Ronald J. Haller
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

✓
N^o 7462

16-43
12-6-61
OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 8/21

RECEIVED OF

A. J. Donald

FEE OF

5⁰⁰

FOR WHICH PERMISSION IS GRANTED

J. B. Oberlin

TO TAP

San

SEWER ON THE

W.

OF

Clearmont NE

AVE.

ST. TYPE OF STREET

Rec'd

THE PREMISES BEING LOT NO.

11335

HOUSE NO.

2141

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

A. J. Donald

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.