Nº 7475

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9-20-61	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 319	The state of the s	
SIZE OF PIPE USED 6 11	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT LAST A	
WAS LATERAL AT CURB? YES		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR N. W. Walson	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
	£ 60 2 12 1	
	The second secon	
(Times		
	92	
\mathcal{N}	12 2/7/	
	<u> — ф</u>	
SIGNED REL Lathern	FILED AT ENGINEER'S OFFICE	
INSPECTOR FOR CIT		
PE44 PV6		

Nº 7475

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	ASSILLON, OHIO, Sept 15 1
FOR WHICH PERMISSION IS GRANTED	
TO TAP DAID. SEWE	RONTHE DAUTH
OF 1/032/ // 17 AVE. TYPE	OF STREET ALCOH
THE PREMISES BEING LOT NO. 154/	, HOUSE NO. 319
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NOT THE DEPARTMENT OF PUBLIC SERVICE.	Io. 2323, DULY PASSED BY THE CITY COUNCIL, AND

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.