## Nº 7478

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9-40-61	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 608	
SIZE OF PIPE USED //	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 76 SOUTH of MY DEC
WAS LATERAL AT CURB? YS	· · · · · · · · · · · · · · · · · · ·
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR A Necus
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.	
	16
(2.1, 2.1, 2.1, 2.1, 2.1, 3.1, 3.1, 3.1, 3.1, 3.1, 3.1, 3.1, 3	The state of the s
V	1/20/26
	$\langle -76' \rangle$
SIGNED Roy Latham	
INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE
REMARKS	

## Nº 7478

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

9/20
MASSILLON, OHIO, / X O 1
RECEIVED OF a. A. Arana FEE OF \$5"
FOR WHICH PERMISSION IS GRANTED ACTOR OF BLAR
A
TO TAP Land. SEWER ON THE
of 21th 7111) AVE. TYPE OF STREET dirk
THE PREMISES BEING LOT NO. 12052 , HOUSE NO. 608
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

Note: This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.