

Nº 7486

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-23-61

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 2133

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


40' NORTH OF H/O SANDY 8' 0"

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR H. Urban

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED _____

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

11-30-61

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

Nº 7486

MASSILLON, OHIO, Oct. 18 1961

RECEIVED OF Harry B. Urban FEE OF \$ 5.00

FOR WHICH PERMISSION IS GRANTED from Sept

TO TAP San SEWER ON THE West

OF Clearview NE AVE. ST. TYPE OF STREET Alley

THE PREMISES BEING LOT NO. 11385 HOUSE NO. 2133

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

an

NAME OF CONTRACTOR Harry B. Urban

Note: This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.