

Nº 7502

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 11-6-61

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

272' SOUTH OF MH 8'DEEP

HOUSE NO. 300

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR Laughlin

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

William Hammer

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

✓ 3/9/69
00

Nº 7502 ✓

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, Mar. 2 1

RECEIVED OF Luedd Co.

FEE OF \$ 5.00

FOR WHICH PERMISSION IS GRANTED _____

TO TAP San.

SEWER ON THE _____

OF Arthur St

AVE.
ST. TYPE OF STREET Dist

THE PREMISES BEING LOT NO. Lot # 28 Bl 326

HOUSE NO. 300

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Laughlin

Note: This permit covers work outside of building only. Any work :
walls of building is subject to Massillon Board of Health Regulations.