Nº 7506

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

18/ 205 CUR

**	7 1 10 10 10 10 10 10 10 10 10 10 10 10 1
DATE INSPECTED _//- 20-1/	IF SO HOW AND LOCATION FROM N.W. of M. in H 70
HOUSE NO. 809	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? Ves	· · · · · · · · · · · · · · · · · · ·
	NAME OF CONTRACTOR H. URBAN
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
	170
. The constant of the state of the constant of the state	As Co. In Co.
	73/13/
	Q ASIL
Port Lathan	
SIGNED OF CIT	FILED AT ENGINEER'S OFFICE
DEMARKS	

1-19-62 5-4

Nº 7506

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON, OHIO, 17
RECEIVED OF LANGE	110 Au FEE OF \$500
	Me Faddew
TO TAPSE	WER ON THE OALLE
OF RIMINE 111.71 & AVE. TY	•
THE PREMISES BEING LOT NO. 8095	. HOUSE NO. 809
WORK TO BE DONE IN ACCORDANCE WITH ORDINANC OF THE DEPARTMENT OF PUBLIC SERVICE.	E No. 2323, DULY PASSED BY THE CITY COUNCIL, AND

Note: This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.