Nº 7520

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 4-12-62	IF SO HOW AND LOCATION FROM WYE 72 EAST OF 1/4 10/6		
HOUSE NO. 17/4	PINST MANROLE DOWN STREAM		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEFTH		
WAS LATERAL AT CURB? 10			
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR D. POGERS		
SHOW BY DIAGRAM RELATION OF LATER	RAL TO WALL OF BUILDING SERVED. $ec{ec{\gamma}}$		
1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	₹7°serp		
	1€-15 BEND		
The state of the s	10'DEEP 46		
	0 72'		
SIGNED POLY TIME INSPECTOR FOR CITY	FILED AT ENGINEER'S OFFICE		
REMARKS DITCH FILLEN WITH	Grund		

Nº 7520

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

		A STATE	MASSILLON, OHIO,
	RECEIVED OF	Dale	Rayers J. J. S. FEE OF \$ 5
· · · · • <u>-</u>	OR WHICH PERMISSION	IS GRANTED III.A.	Seda Co
	O TAP	U	SEWER ON THE
0	F Derma	nd DE	AVE. ST. TYPE OF STREET A 1 h
. τ	HE PREMISES BEING LO	r No. 6165	HOUSE NO
			ADDIVANCE NO 2222 DULY PAGGED BY THE CITY COUNCIL AN

OF THE DEPARTMENT OF PUBLIC SERVICE.

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.