Nº 7522

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	FIRST MANHOLE DOWN STREAM WVF 15 EAST OF 14 8 13			
HOUSE NO	FIRST MANHOLE DOWN STREAM WYE 75 SAST 2777 7.72			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH			
WAS LATERAL AT CURB?				
WAS ATTACHED TO MAIN VES	NAME OF CONTRACTOR D, POGERS			
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.				
	S6 TOFF			
	9/5' 7/6'			
SIGNED PAY INSPECTOR FOR CITY	FILED AT ENGINEER'S OFFICE			
REMARKS DITOH FILLED	WITH GRAVE!			

Nº 7522

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

in a Million of the Committee of the Com	MASSILLON, OHIO,	1
 RECEIVED OF Hales A. A. A.	ere + Lon	EE OF \$ 5
FOR WHICH PERMISSION IS GRANTED	1. Bera Co	
TO TAP (and) SEV	WER ON THE	* **
OF CAME AVE. TYPE	PE OF STREET 114	:
THE PREMISES BEING LOT NO. 640	, HOUSE NO. 1916	2
WORK TO BE DONE IN ACCORDANCE WITH ORDINANC	E No. 2323, DULY PASSED BY THE CIT	Y COUNCIL, AND

Note: This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.

A FLORIDA CONTRACTOR AND A MENTER OF MENTER OF