

Nº 7537

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 4-4-62

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 504

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB-LINE AND DEPTH

212' NORTH OF MA 7 1/2' DEEP



WAS LATERAL AT CURB? Prop Yes

Prop

WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR Joe & Joe

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Roy Nathan
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

✓
Nº 7537

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, April 2 1911

RECEIVED OF

Geo Geo

FEE OF \$ 5⁰⁰

FOR WHICH PERMISSION IS GRANTED

Randazzo & Whitman
00

TO TAP

San

SEWER ON THE

East

OF

Washington

S.E.

AVE.
ST. TYPE OF STREET

dist

THE PREMISES BEING LOT NO.

11617

HOUSE NO.

504

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Geo Geo

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.