Nº 7538

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 4-5-62	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO. 368	DISTANCE FROM FIRST MANHOLE		
SIZE OF PIPE USED 6	CURB LINE AND DEPTH 129 NOVIH OF MY 8/2 NEEP		
WAS LATERAL AT CURB?	Prop		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR TOE \$ TOE		
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.			
	70651		
N -	53.		
	87,0000/C		
SIGNED ROY SIGNED INSPECTOR FOR CITY	FILED AT ENGINEER'S OFFICE 1291		
REMARKS			

Nº 7538

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLO	DN, OHIO, april = - 1
RECEIVED OF	Gre _	FEE OF \$
	Stanley The	
FOR WHICH PERMISSION IS GRANTED.	//	
TO TAP Salu.	SEWER ON THE	· Cart
OF Garlynn VE.	AVE. ST. TYPE OF STRE	ET Chit
THE PREMISES BEING LOT NO. 1/6		
	1	3. DILLY PASSED BY THE CITY COUNCIL, AND

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR CYCY

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.