Nº 7541

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-30-66	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO. 4/1	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 36 EAST OF MF 83 DEES		
WAS LATERAL AT CURB? VES			
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR CL DIAWA		
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.			
	JOEE P 160		
	120' X 820 5EP		
/V	Circum 3 6		
SIGNED POLY INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE		
REMARKS			

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	1 /
	$\angle I$.
•	MASSILLON, OHIO, //U
and the second of the second o	
$\mathcal{L}_{\mathcal{L}_{\mathcal{L}}}$	
RECEIVED OF	FEE OF SU
$(1/1)_{3}$	R. Q Charles
FOR WHICH PERMISSION IS GRANTED	1 1 A COLORO
Total Jan	SEWER ON THE
	IEWER ON THE
of there ne AVE.	TYPE OF STREET CCCC
~	
THE BEEMISES BEING LOT NO. 1/50/	. / //
THE PREMISES BEING LOT NO.	HOUSE NO.
WORK TO BE DONE IN ACCORDANCE WITH OPDINA	NCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AN
	TOE ING. 2020, DULT PASSED BY THE CITY COUNCIL, AN
OF THE DEBARTMENT OF PUBLIC SERVICE	

NAME OF CONTRACTOR

Note: This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.