## Nº 7561

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM 268 E OF H 10 DEE
HOUSE NO	
SIZE OF PIPE USED 6 11	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH
WAS LATERAL AT CURB? // 0	and the control of the control of the property of the control of t
WAS ATTACHED TO MAIN YES	NAME OF CONTRACTOR SOI MONASTIC
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
<b>N</b>	
	">'o.
4.5 (1.3)	the state of the s
<u>+</u>	10'0,
	Q 268' 4/22'
Ray Zatta	
SIGNED INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE
REMARKS	

## Nº 7561

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	6/,	
	Massillon, Ohio,1	
RECEIVED OF The M	anastral FEE OF \$ 5 A	
FOR WHICH PERMISSION IS GRANTED Mars. Bld. Co.		
TO TAP LAW	_ SEWER ON THE	
of Vermont DE AS	T. TYPE OF STREET dirk	
THE PREMISES BEING LOT NO. 6/62	. HOUSE NO. 1700	
WORK TO BE DONE IN ACCORDANCE WITH ORDIN OF THE DEPARTMENT OF PUBLIC SERVICE.	NANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.