

Nº 7574

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6-9-62

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM WYE 27' W. OF M/G 1/2'

HOUSE NO. 2315

SIZE OF PIPE USED 6"



DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? NO

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR R. Mark

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 7574

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, June 9 1911

RECEIVED OF R. G. Marks

FEE OF \$ 5

FOR WHICH PERMISSION IS GRANTED Leaded Cops.

TO TAP San.

SEWER ON THE South

OF Rhode Island S.E.

AVE.
ST. TYPE OF STREET

Oiled

THE PREMISES BEING LOT NO. 12331

HOUSE NO. 7315

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR R. G. Marks

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.