Nº 7575

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 6-11-67	IF SO HOW AND LOCATION FROM WYF 194 EOSM 9
HOUSE NO. 1850	DISTANCE FROM FIRST MANHOLE
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? N 6	
WAS ATTACHED TO MAINS	NAME OF CONTRACTOR ne monastra
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING SERVED.
	- 1
	0 194 4/12
SIGNED ROY Latton	FILED AT ENGINEER'S OFFICE
INSPECTOR FOR CI	
REMARKS	

Nº 7575

OFFICE OF THE DIRECTOR OF PUBLIC SE: PERMIT TO TAP SEWER

	6/0
	MASSILLON, OHIO,
RECEIVED OF	FEE OF \$5
FOR WHICH PERMISSION IS GRANTED THE	· · · · · · · · · · · · · · · · · · ·
k was	7/
OFSEW	E OF STREET
THE PREMISES BEING LOT NO.	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE OF THE DEPARTMENT OF PUBLIC SERVICE.	No. 2323, DULY PASSED BY THE CITY COUNCIL, AN

NAME OF CONTRACTOR

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.