## Nº 7583

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7-9-62	IF SO HOW AND LOCATION FROM 46' WEST OF MH 91 DEEP
SIZE OF PIPE USED 6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? NO	l M a Fra
WAS ATTACHED TO MAIN VES	NAME OF CONTRACTOR LOG MANASTRA
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
en e	7'0EE0
	N UP STREAM 3' DEED
SIGNED WILLIAM MANU INSPECTOR FOR CITY	MAFILED AT ENGINEER'S OFFICE
REMARKS	•

N? 7583

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	(0/10	
	MASSILLON, OHIO,	
RECEIVED OF THE M	on estral FEE OF S 5	
FOR WHICH PERMISSION IS GRANTED M	and Blily Co	
TO TAP. A am	SEWER ON THE	
OF Maro LE. AL	/E. T. TYPE OF STREET AUX	
THE PREMISES BEING LOT NO. 6357	7	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, ANI		
OF THE DEPARTMENT OF PUBLIC SERVICE.		
Name of Contractor	inactro)	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.