

Nº 7598

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 7-10-62

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 229' NORTH OF MH 10' DEEP

HOUSE NO. 301

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR R. G. MARKS

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED William Hammer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 7598

OFFICE OF THE DIRECTOR OF PUBLIC SE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

RECEIVED OF

R. J. Marks

July 5

FEE OF \$

5

FOR WHICH PERMISSION IS GRANTED

Lueddell Co.

TO TAP

Sew.

SEWER ON THE

West

OF

Hudsonville Dr. S.E.

AVE.

ST. TYPE OF STREET

dirt

THE PREMISES BEING LOT NO.

12328

HOUSE NO.

301

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AN
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

R. J. Marks

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.