FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

TOPPO (1)	ING DATA TO BE ANSWERED BY INSPECTOR
Nº 7622	AND SIGNED WHEN RETURNED
<i>)</i> *•	
DATE INSPECTED 1-5-62	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 2023	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 36 N. 15 MH 9 DEEX CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR H. M. Alexan
SHOW BY DIAGRAM RELATION OF LATER	RAL TO WALL OF BUILDING SERVED.
	· · · · · · · · · · · · · · · · · · ·
	70.
	No experience of the second se
J	60
	40
	and the state of t
Roy	36'-1
SIGNED INSPECTOR FOR CITY	FILED AT ENGINEER'S OFFICE
V /	
REMARKS OCC 8/62	

Nº 7622

PERMIT TO TAP SEWER

RECEIVED OF Rotert C	beilin FEE OF 5
FOR WHICH PERMISSION IS GRANTED	arold Mª Callum
of Charrier 71.6.	SEWER ON THE West
THE PREMISES BEING LOT NO. 11490	, HOUSE NO. 2023

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AN OF THE DEPARTMENT OF PUBLIC SERVICE.

AME OF CONTRACTOR (1.) CAU

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.