

Nº 7636

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-11-62

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 7229

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 7' W. OF H 7' DEEP

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR H. Urban

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



7'

R 7'0"

38'

45° BEND
7' DEEP

SIGNED

Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

Nº 7636 ✓

7-4.
12-21-6.
OFFICE OF THE DIRECTOR OF PUBLIC SE
PERMIT TO TAP SEWER

MASSILLON, OHIO.

Oct 10

RECEIVED OF

George Hastler

FEE OF \$

5^c

FOR WHICH PERMISSION IS GRANTED

Robert Hastler

TO TAP

San

SEWER ON THE

South

OF

Aster W.

AVE.

ST. TYPE OF STREET

chit

THE PREMISES BEING LOT NO.

7754-53

HOUSE NO.

7229

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Harry Urban

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.