

Nº 7639

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-30-62

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 25

SIZE OF PIPE USED 4"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 499' E. OF THE EAST CURB OF E


WAS LATERAL AT CURB? PROP. LINE YES

5 1/2' DEEP

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR R. REMLEY

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Roy Lothman
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

OLD RUBBLE REMOVE & SAND HAULED IN TO COVER

2/20/64

Nº 7639 ✓

OFFICE OF THE DIRECTOR OF PUBLIC SEWERS
PERMIT TO TAP SEWER

MASSILLON, OHIO, Oct. 30,

RECEIVED OF

Raymond Sewley

FEE OF \$

52

FOR WHICH PERMISSION IS GRANTED

Humble Oil Co.

TO TAP

Sani.

SEWER ON THE

South

OF

Cherry Rd. N.E.

AVE.

ST. TYPE OF STREET

Res.

THE PREMISES BEING LOT NO.

30-31-732

HOUSE NO.

25

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Raymond Sewley

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**