

Nº 7640

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-31-62

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

PUTWYE IN MAIN 156' W. OSU
STREAM @ BRIDGE WARWICK

HOUSE NO. 21

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR R. REMLEY

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Roy Latham

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS CLAY SOIL WHICH WAS FILLED. USED GRAVEL & BLACKTOP TO
FIX STREET.

✓
Nº 7640

2/20/64 OD
OFFICE OF THE DIRECTOR OF PUBLIC SEWERS
PERMIT TO TAP SEWER

MASSILLON, OHIO, Oct. 30, 1964

RECEIVED OF Raymond Penley

FEE OF \$ 5.00

FOR WHICH PERMISSION IS GRANTED Thomas Foster

TO TAP Sanis.

SEWER ON THE South

OF Warwick St. N.O.

AVE.

ST. TYPE OF STREET dirt

THE PREMISES BEING LOT NO. # 3544

HOUSE NO. 21

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Raymond Penley

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**