Nº 7642

REMARKS _

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10-2-62 HOUSE NO. 309	DISTANCE FROM FIRST MANHOLE DOWN STREAM DOWN STREAM TO DITCH AT 1921 NORTH OF MY 121 DEEP
SIZE OF PIPE USED	CURB LINE AND DEPTH 193 NORTH 117 14 114 114
WAS LATERAL AT CURB? YES	
	NAME OF CONTRACTOR JOE 4 JOE
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR 1
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
	TN SALES AND SAL
na mengalah sebagai kecamatan dan kecamatan berasak berasak berasak berasak berasak berasak berasak berasak be Berasak	81 / 12/1
	192
SIGNED William Hamm	FILED AT ENGINEER'S OFFICE
INSPECTOR FOR CIT	🔭 Borner (1980)

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

MASSILLON, OHIO, 77.
RECEIVED OF Jac + Jac FEE OF \$ 5
FOR WHICH PERMISSION IS GRANTED Fudded Co.
TO TAP Savi. SEWER ON THE What
of Arthur ST. TYPE OF STREET dert
THE PREMISES BEING LOT NO. 13378 , HOUSE NO. 307
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, ANI

OF THE DEPARTMENT OF PUBLIC SERVICE.

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.