

Nº 7643

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-2-62

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 2213

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN —

NAME OF CONTRACTOR JOE & JOE

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N
↓



SIGNED William Hammer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 7643 ✓

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO.

Nov. 7.

RECEIVED OF

Joe & Joe

FEE OF \$ 5.00

FOR WHICH PERMISSION IS GRANTED

Ludda Co.

TO TAP

Sani.

SEWER ON THE

West South

OF

Cambridge

AVE.

ST. TYPE OF STREET

dent

THE PREMISES BEING LOT NO.

12379

HOUSE NO.

2218

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Joe & Joe

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.