

Nº 7645

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-1-62

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 2200

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 243' WEST of MH 5' DEEP

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR JOE & JOE

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED _____

William Hammer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 7645 ✓

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, Feb. 7,

RECEIVED OF Joe + Joe

FEE OF \$ 5.00

FOR WHICH PERMISSION IS GRANTED Ladd & Co.

TO TAP Sani.

SEWER ON THE South North

OF Cambridge S.E.

AVE.
ST. TYPE OF STREET

dirt

THE PREMISES BEING LOT NO. 12382

HOUSE NO. 2200

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Joe + Joe

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.