

Nº 7646

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-4-62

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 2208

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

170' WEST OF MH 7' DEEP


WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR JOE & JOE

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N
4



SIGNED _____

William Hammer

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 7646 ✓

OFFICE OF THE DIRECTOR OF PUBLIC SEWERS
PERMIT TO TAP SEWER

MASSILLON, OHIO, Nov. 7.

RECEIVED OF Joe + Joe

FEE OF \$

FOR WHICH PERMISSION IS GRANTED Liddell & Co.

TO TAP Sani.

SEWER ON THE South NORTH

OF Cambridge

AVE.
ST. TYPE OF STREET driv

THE PREMISES BEING LOT NO. 13383

HOUSE NO. 2208

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Joe + Joe

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**