Nº 7651

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 11-28-62	IF SO HOW AND LOCATION FROM STUBIN M	6 /2 DEED
HOUSE NO. 204 SIZE OF PIPE USED 6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	<u> </u>
WAS LATERAL AT CURB? //6	NAME OF CONTRACTORE, LAU	GHLIN
SHOW BY DIAGRAM RELATION OF LATE		17
	— N	Ne
	en en general de la companya de la c La companya de la co	•
SIGNED Roy Jatam INSPECTOR FOR CI	FILED AT ENGINEER'S OFFICE	r-10'BEP
· · · · · · · · · · · · · · · · · · ·		

Nº 7651

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

$11/_{10}$
MASSILLON, OHIO,
RECEIVED OF FAILABLE Consisting FEE OF \$ 5
FOR WHICH PERMISSION IS GRANTED IN A CUTLA
TO TAP DEWER ON THE
of 21 pt DE. AVE. TYPE OF STREET duit
THE PREMISES BEING LOT NO. 12350
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, ANI
OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR OF THE ALL

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.