Nº 7666

REMARKS

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 2-3-63	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 22/	
SIZE OF PIPE USED 4110	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH OLD LATIS RAL S 10/5
WAS LATERAL AT CURBY VES	· · · · · · · · · · · · · · · · · · ·
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR A. DIANA
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING SERVED.
	₹
V	SOUTH CURR 3
War Hanne	

Nº 7666

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

RECEIVED OF_	Cample	Lee	MASSILLON	OHIO, Colic	FEE OF \$5
FOR WHICH PERMISSIO	/ /	<i>(</i>		il G.	FEE OF 3
TO TAP Man		s	EWER ON THE_	South	<u> </u>
or South.	20	AVE. ST. T	YPE OF STREET	Hard	Jurface
THE PREMISES BEING I				, HOUSE NO.	21
WORK TO BE DONE IN	ACCORDANCE WIT	H ORDINAN			HE CITY COUNCIL, AN

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.